

To: All Authorized Business Partners Date: April 12, 2011

Subject: Technical Training Announcement

Product: D074/D075 and M044 Light Production Color MFP and Printer

Training Format: Instructor-led Training

Product Code	Lanier	Ricoh	Savin		
D074	Pro C651EX				
D075	Pro C751EX				
M044	Pro C751				

The Ricoh Family Group is pleased to announce the release of the new D074, D075 and M044 color light production MFPs and Printer.

The D074 and D075 are multi-function copiers, and the M044 is a printer. These units are Ricoh's new flagship light production line-up. They feature heavy production-class features, such as, an improved customizable paper library, enhanced TCRU, and a more powerful Fiery Controller. In addition, features found on Ricoh's heavy-production machines, such as enhanced image quality with chemical toner, oilless fusing, and expanded finishing options, are also available on this series.



# **Training Prerequisites**

Service professionals seeking certification on the D074/D075/M044 will be required to meet one of the following options:

# Option 1

Certification on one of the following:

G178/D016/D095/M077 D014/D015 Color Series D023/D027/D037

D104/D088/D086

AND

Fiery Solutions V2 (after 11/1/09)

## Option 2

Certification on one of the following:

DDP70/92 DDP184 EMP156 D059

AND

Digital Color Basics *OR* Digital Color Competency

AND

Fiery Solutions V2 (after 11/1/09)






# **Final Certification**


In order to achieve final certification on the D074/D075/M044, all service professionals must have completed the Fiery Solutions V2 certification after November 1, 2009 or the Fiery E41/E81 Self Paced Update, if eligible. Fiery Solutions V2 certification can be completed prior to, or after taking the D074/D075/M044 instructor-led course, however, certification will *NOT* be issued until the Fiery Solutions V2 course is successfully completed.

## **Prerequisite Maps**





#### TRACK B





# **Prerequisite Models**

	<b>-</b>				
Product Code	Gestetner	Lanier	Ricoh	Savin	
G178/D016	Pro C900/Pro C900s				
M077/D095	Pro C901/Pro C901s				
M078/D097	Pro C720/Pro C720s				
D014/D015	N/A	LD260c/LD275c	MP C6000/7500	C6055/7570	
D078/D079	N/A	Pro C550EX/Pro C700EX			
D023	MP C2800	LD528C	Aficio MP C2800	C2828	
D025	MP C3300	LD533C	Aficio MP C3300	C3333	
D027	MP C4000	LD540C	Aficio MP C4000	C4040	
D029	MP C5000	LD550C	Aficio MP C5000	C5050	
D037	MP C2030	LD520CL	Aficio MP C2030	C9020L	
D038	MP C2050	LD520C	Aficio MP C2050	C9020	
D040	MP C2530	LD525CL	Aficio MP C2530	C9025L	
D041	MP C2550	LD525C	Aficio MP C2550	C9025	
D086	MP C3001	LD630C	Aficio MP C3001	C9130	
D087	MP C3501	LD635C	Aficio MP C3501	C9135	
D088	MP C4501	LD645C	Aficio MP C4501	C9145	
D089	MP C5501	LD655C	Aficio MP C5501	C9155	
D104	MP C2051	LD 620C	Aficio MP C2051	C9120	
D106	MP C2551	LD 625C	Aficio MP C2551	C9125	
G150/G151	DDP70/DDP192				
G152	DDP184				
G155	EMP156				
D059	Pro 907EX				
D060	Pro 1107EX				
D061	Pro 1357EX				

If you have any questions regarding this or any other training, please visit the Ricoh University web site at <a href="https://www.ricohuniversity.com">www.ricohuniversity.com</a> or contact Ricoh University at (973) 882-2200.

